


Shallow Gas Wells Drilled and Frac'd Near Rosebud, Alberta

Circles: EnCana Wells Perforated and or Hydraulically Fractured Above the Base of Groundwater Protection before April 2006
Solid dots: EnCana Wells Perforated and or Hydraulically Fractured Above 200m before April 2006



E = approximate location of Ernst property

~ 1 mile

Wellheads

- ✧ Abandoned Wellhead
- ✧ Suspended Gas Wellhead
- ✧ Suspended Oil Wellhead
- ✧ Flowing Gas Wellhead
- Location Wellhead
- Flowing Oil Wellhead
- ✕ Miscellaneous Wellhead
- ✧ Water Wellhead
- ✧ Well Downhole Location
- ✧ Newly Licenced Well
- ✧ Newly Spudded Well

High Pressure Pipelines

- Gas Pipeline
- Oil Pipeline
- Water Pipeline
- LVP/HVP Pipeline
- Foreign Pipeline (Only when a company is specified.)

Low Pressure Pipelines

- Gas Co-op Pipeline

