


# Shallow Gas Wells Drilled and Frac'd Near Rosebud, Alberta

Circles: EnCana Wells Perforated and or Hydraulically Fractured Above the Base of Groundwater Protection before April 2006

Solid dots: EnCana Wells Perforated and or Hydraulically Fractured Above 200m before April 2006



High Pressure Pipelines and Wells current to December 31, 2010. Low Pressure Pipelines current to November 1, 2005

E = approximate location of Ernst property

~ 1 mile

Blue box = Rosebud Community Water Tower that exploded in 2005

### Wellheads

- ⊗ Abandoned Wellhead
- ⊗ Suspended Gas Wellhead
- ⊗ Suspended Oil Wellhead
- ⊗ Flowing Gas Wellhead
- ⊗ Location Wellhead
- ⊗ Flowing Oil Wellhead
- ⊗ Miscellaneous Wellhead
- ⊗ Water Wellhead
- ⊗ Well Downhole Location
- ⊗ Newly Licenced Well
- ⊗ Newly Spudded Well

### High Pressure Pipelines

- Gas Pipeline
- Oil Pipeline
- Water Pipeline
- LVP/HVP Pipeline
- Foreign Pipeline (Only when a company is specified.)

### Low Pressure Pipelines

- Gas Co-op Pipeline

N

